

PINPOINT



** Prior to use all bags should be thoroughly checked to ensure there are no issues. At a minimum check for rips or tears in the fabric, the seams to ensure stitching is not compromised, and the webbing slings and lifting eyes.

A – The lifting Sling / Eyes - This is the only point that the bag should be lifted from whilst it is loaded. This must be done in accordance with point C (WLL Label) and should never exceed the value shown. Where there are two Eyes that meet on the bag the WLL is only valid if both are used simultaneously. If there is just one lifting Eye the WLL covers the use of just one. In the case of a Vertical/Horizontal Bag, the WLL applies to either using the two Horizontal Slings at the same time or use of the single Vertical Eye. When lifting the bags, we recommend not lifting on the weld point of the metal circle.

B – Secondary Handles – These are NOT load rated, they are not for use while the bag is loaded. They are designed to assist with moving whilst the bag is empty, or for helping to open the bags once positioned. These are not covered by the WLL.

C – WLL Label – This label advises of the Working Load limit for the bag. To remain compliant this should never be exceeded. This label also contains images of what should and shouldn't be loaded.

- To prevent degradation of the bag material, ensure the bags are stored out of direct UV light and in dry conditions, away from heat sources. We recommend bags are cleaned after each use using fresh water, if required use neutral detergent and a soft cloth to remove any salts or abrasives.
- Keep bags away from sharp objects when storing and when in use
- Do not use the bags to lift or store alkaline or acidic based chemicals or use in chemical based environments.

Company Registration: 6847418

A Limited Company registered in Wales:
Unit 3A, Croffy Industrial Estate,
Penclawdd, Swansea, SA4 3RS



VAT Registration: 986 5601 76

General Office 09.11.2022v3